

# FIELD INSPECTION REPORT

|                        |                                                         |                       |             |
|------------------------|---------------------------------------------------------|-----------------------|-------------|
| Date of Inspection :   | 02/12/2020                                              | District:             | Rohas       |
| Division :             | R.W.D-Bikramganj                                        | Length (km):          | 3.20 km     |
| Name of the Road:      | TDI to Arthu via Koraiga                                |                       |             |
| Scheme/Programme:      | MAINTENANCE                                             | five year maintenance |             |
| Package No.:           |                                                         | Road Id No.:          | 1030/300826 |
| Status of the Project: | Ongoing/Completed/Under Maintenance                     |                       |             |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance five year MR |                       |             |

| Sl. No. | Parameters to be checked                                                                                        | Remarks       |
|---------|-----------------------------------------------------------------------------------------------------------------|---------------|
| 1.      | <b>Pavement</b>                                                                                                 |               |
| a)      | Road Junction condition                                                                                         | ✓ S/U         |
| b)      | Condition of Surfacing                                                                                          | ✓ S/U         |
| c)      | Riding Quality                                                                                                  | ✓ S/U         |
| d)      | Road Camber                                                                                                     | ✓ S/U         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | N/A Yes/No    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                | N/A Yes/No    |
| g)      | Compaction of flank/slope & raincuts if any                                                                     | ✓ Yes/No      |
| 2.      | <b>Cross Drainage</b>                                                                                           |               |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                            | ✓ S/SRI/U     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | ✓ S/SRI/U     |
| c)      | Condition of railings/slab/approach for Bridges                                                                 | ✓ S/SRI/U     |
| 3.      | <b>Road Furniture</b>                                                                                           |               |
| a)      | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m ✓ Yes/No |
| 4.      | <b>Compliance History</b>                                                                                       |               |
| a)      | Status of ATR's & any others                                                                                    | N/O           |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | (S) |
| Satisfactory but requires Improvement (SRI) |     |
| Unsatisfactory (U)                          |     |

Ravi M  
02/12/2020  
(Signature)

NAME: Ravi M Kumar