FIELD INSPECTION REPORT

Date of I	aspection :		A		
Division: Delaga:			District: Kohtas		
Name of the Road: Pord Road Bersawaan Kala Besserni Kala					
Scheme/	, rogramme:	MAINTENANCE	Besaini Ka	In Lund	
Package No.:					
Status of the Project: Oneging/Complete/Harles Maintenance					
Work is a case of: New Connectivity/Up gradation/ Maintenance					
SI. No.	Parameters to be checked			Remarks	
1.	Pavement				
3)	Road Junction condition			S/U	
ь)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement,			Yes/No	
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
ь)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Rond Furniture				
n)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History			77	
a)	Status of ATR	l's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Om Prakash Kumar

DESIGNATION: J.E