## HZ2d HS - HM dl FIELD INSPECTION REPORT

Date of Inspection:	2/12/20	District: AURAHCA PAO
Division: 0 000	INCFI	Length (km):
Name of the Road:	HABBU	ROB MORT - MALNA
Name of the Road: Scheme/Programme:	MAINTENANO	CE MORE - MALVOR
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Comp	leted/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	/ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	/ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U /	
c)	Condition of railings/slab/approach for Bridges	, S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No .	
4,	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	

(Signature)

NAME: Bropert Knaw Su porto

DESIGNATION: