FIELD INSPECTION REPORT

		ARAN
vision :	TOUR WAY LOUIS I LENGTH (KIII).	2.00 km.
homo/D	he Road: Gaura to Hathicar hote hue Ro rogramme: MAINTENANCE	yeudra Singh Ke Chingmi tal
ckage I		1306500821
	the Project: Ongoing/Completed/Under Maintenance	
	rease of: New Connectivity/Up gradation/ Mainte	0 11
l. No.	Parameters to be checked	Remarks
1.	Pavement	A CONTRACTOR OF THE CONTRACTOR
a)	Road Junction condition	\S/U
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA:
d)	Road Camber	S/U MA
e)	Whether free from defects such as visible crac aggregates in case of CC Pavement.	ks, exposed Yes/No NA.
f)	Contraction Joints provided or not (CC Pavement)	- Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	- Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including	g its painting S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC cul	verts S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/stones/Pavement road markings are provided and main	km & 200m tained Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	~.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

work is on going. -

NAME:

DESIGNATION:

Scanned with CamScanner

(Signature)