FIELD INSPECTION REPORT

	<u>F1</u>	ELD INSPECTION	N REPORT		
				Broppen	
Division	n Pros		Length (km):	3 0 200	
Name o	f the Road:	construction of Re		nardani Rosa	
Scheme/Programme		MAINTENANCE			
Package	No .: RM/13H/PIR/	19/0012	Road Id No.: 1040120	1005	
Status of the Project :		Ongoing/Completeted/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/Maintenance			
SI No.	F	Parameters to be checked		Remarks	
1	Pavment				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			✓S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U №A	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U NA	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U 🕈 🛧	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4	Compliance History				
a)	Status of ATR's & any others			110	

Overall	Ratin	g
---------	-------	---

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:

ASKKMO

(Signature)

Desigination

2000 10 Mg