HH98 MT-LA ROMAI - HATELY YOU FIELD INSPECTION REPORT

The state of the s	DAVIN	2/12/20 Actd	District: AURANGA  Length (km): 7	13/11)	
ame of the	Road:	HH 97 LAVAU	1015114 1134 1414	1 0 1	
cheme/Prog		MAINTENANCE	Police 2010	A CON	
ackage No.	THE PARTY OF THE P		Length (km): 3.85  POLY HA - INAMANA  Road Id No.:  ed/Under Maintenance		
tatus of the	STORY THE PARTY OF	Ongoing/Complete	ed/Under Maintenance		
ork is a ca	se of:	CANADA CONTRACTOR OF THE PROPERTY OF THE PARTY OF THE PAR	/Up gradation/ Maintenance		
il. No.		Parameters t	Parameters to be checked		
	Pavement				
a) Ro	Road Junction condition			S/U	
b) Co	Condition of Surfacing under			S/U	
c) Ri	Riding Quality			S/U	
d) Ro	Road Camber Road			S/U	
61	Road Junction condition  Condition of Surfacing  Riding Quality  Road Camber  Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f) Co	Contraction Joints provided or not (CC Pavement)			Yes/No	
g) Co	Compaction of flank/slope & raincuts if any			Yes/No	
2. C	Cross Drainage				
a) C	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b) C	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c) C	Condition of railings/slab/approach for Bridges			, S/SRI/U	
3. R	Road Furniture				
a) W	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4, C	Compliance History				
a) St	Status of ATR's & any others				
<u> </u>					
Overall Rat	mug	Satisfactory (	2 (2) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1	AIA	
			out requires Improvement (SRI)	1	
		Unsatisfactor	y (U)		
	1			On Zall	
				1241	
				Signature)	
	100			Jiguarare)	
	The second second	A			
VAME:	Par	poler f	יין איני וויי		