

FIELD INSPECTION REPORT

Date of Inspection :	5/12/20	District:	Nalanda
Division :	HILSA	Length (km):	5.170 km
Name of the Road:	Telhara Ming Bazar road 4th km to Koshiyawn.		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance Ongoing		
Work is a case of:	New Connectivity/Up gradation Maintenance upgradation		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregate in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Composition of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S R/I	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S R/I	
c)	Condition of railings/slab approach for Bridges	S R/I	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m status Pavement road markings are provided and maintained	No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Satisfactory

NAME: **Anand Kumar Arya**
J.E

(Signature)
5/12/20

Ongoing