		FIELD INSPECTION RE			
			District 1310	JAY	
vision	Piro	,	Length (km): ¿	5.500Km	
lame of the Road:		NH30 to CLAKE	NH30 to CLAKLADLWA VIE KONWON		
heme	Programme /	MAINTENANCE			
ackage	No.: MR-11/19	20 Piro 13 Road I	d No.:		
Status of the Project :			Ongoing/Completeted/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/Maintenance			
I No.		Parameters to be checked		Remarks	
	Payment		Agreeme.	nt not Don	
)	Road Junction condition		S/U		
)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
2)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC oulverts			S/SRI/U	
0)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4	Compliance History				
a)	Status of ATR's	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Raja Ombrakash

Designation Executive Engineer