FIELD INSPECTION REPORT

N 1-1-6T-	namection: / 1919 a.Dr. District: 4 across		<u> </u>
	54 35 164		
	: (W) Division ygonu Length (km): 5.0 Km	,	
200 0.00 0.00 0.00 0.00 0.00 0.00 0.00		Pour Mai	Ma Damdon
	Programme: MAINTENANCE		Ma Dalanda
	No.: MR-N 19-20 Jastely Road Id No.: 284110325	,60	9
Mile Mark Control of 1100 and 1			
Maria de la companya del companya de la companya del companya de la companya de l			
		。 公司 (1)	
a)	Road Junction condition	¢§/U	
b)	Condition of Surfacing	√ 8/U	
c)	Riding Quality	√8/ U	
d)	Road Camber	\ 8/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	¥cs/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No/	
· 14, 12	SCHOOL TO THE SECOND		COLUMN TO THE
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	v
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	s/sri/U-	
	a Koru (Siteriture)		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/Nø	
	Recommendation of the second second		
a)	Status of ATR's & any others	NIW	
			A .

Overall Rating

Satisfactory (S)	18 'S^
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	t 16

(Signature) AE

NAME:

DESIGNATION: