FIELD INSPECTION REPORT

11-ma - 0/1	12/2020	District: Janea	
ate of the P	121202	Length (km): 8.60 KH	ia Gadaham
ivision: Janu	Raigun	Salain Bichgarena chaule	Long gon Po
ame of the Road: Fatch	INTENANCE	Length (km): 8.60 kH Salaizy Bichganua chowle to Agu	7
cheme/110gramma	1- ha	Road Id No.: 2841903355	ST
ackage No.: MK-N/7	going/Completed	I/Under Maintenance	
Ne	w Connectivity/U	Jp gradation Mannethane	
THE RESERVE THE PARTY OF THE PA	rapa attegrati	an atoxic and the second	Remarks
		and the second second	
ig Pavement	A Library		SAUNIA
a) Road Junction con	- tracing condition		
- 41.1 - 6.5.1-60	- u. Conforing		
	2001 (M.)		SAUNIA
*	Riding Quality		
d) Road Camber	Road Camber Whether free from defects such as visible cracks, exposed		Yes/No-
e) aggregates in case	of CC Pavemen	ıt.	Yes/No
	Contraction Joints provided or not (CC Pavement)		
	Compaction of flank/slope & raincuts if any		
g) Compaction of 118	ink/slope & rank	The second secon	TO THE SECOND
15 L Cross Drainage			SYSREMUN
a) Condition of head	Condition of head walls in Hume pipe culverts including its painting		
	Condition of Abutment & Wing walls, Slab in RCC culverts		
The second secon	Condition of railings/slab/approach for Bridges SZ		
Road Barniture		the water has a second	T. C. C.
a) Whether sign b stones/Pavement	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
心 特殊 (compliated til	ioe -		
a) Status of ATR's	Status of ATR's & any others		
		(On-G	oiry'
Overall Rating :	Satisfactory (S		

1011-801	73
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	. 2

Duste	
06/12/2020	A-78=
26	ACTIVIZED.
(Say Bakash Compt	(Signature)

NAME:

DESIGNATION: