## FIELD INSPECTION REPORT

Date of Inspection: 05. 12.2020		District: BANKA
Division: Banka-1		Length (km): 18.40
Name of the Road:	(heshal) Ta	Mapun Jilani Road.
cheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 20703508107
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U/
d)	Road Camber	\$/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	VI CONTITO
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	Yes/No
a)	Status of ATR's & any others	Take 1

Overall Rating :

Unsatisfactory (U

(Signature)

NAME:

DESIGNATION: