FIELD INSPECTION REPORT

Date of	Inspection: 6/12/2020 Distr	ict: Jamus	
Division: Jamus Length (km):		34,01364	
	Silve no. di		
	Programme: MAINTENANCE	to Dymorkola	
Package		Id No.: 20804108173	
	f the Project: Ongoing/Completed/Under		
1.5	a case of: New Connectivity/Up grad	·V	
- 5 CM			Pomrks.
SINNO	Transcorer of the second secon		in a light of the
1	Pavement		de el marve de
a)	Road Junction condition		_S/U
b)	Condition of Surfacing		√S/U
c)	Riding Quality		√8/U
d)	Road Camber		√S/U
e)	Whether free from defects such as aggregates in case of CC Pavement.	visible cracks, exposed	Yes/No
f)	Contraction Joints provided or not (CC Par	vement)	Yes/No
g)	Compaction of flank/slope & raincuts if an	ny	Yes/No
1 2	Gross Drainige		
a)	Condition of head walls in Hume pipe culv	verts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Sla		S/SRI/U
c)	Condition of railings/slab/approach for Bri		S/SRI/U
	Road Burnffure		
a)	Whether sign boards/informatory/caution stones/Pavement road markings are provide	led and maintained	Yes/No
相小學和	Complicate History	HOLES AND THE STREET OF THE STREET	TO SERVICE THE SERVICE OF THE SERVIC
a)	Status of ATR's & any others		HIA

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature) Ho

NAME:

DESIGNATION: