FIELD INSPECTION REPORT

Date of Inspection: A. 12, 20 District: Yay' Leh'			
Division: Mahw Length (km): 5.50 km		1 Ndampn	
Name of the Road: Bellow of the North to Marta Labor Hor More			
MATTERANCE WORK TO			
Package No.: 0 5 19 - 20 Road Id No.:			
Status of the Project: Ongoing/Completed/Under Ma		Inder Maintenance	4.5
· · · · · · · · · · · · · · · · · · ·		gradation/ Maintenance	Remarks
Sl. No. Parameters to be checked			
1.	Pavement	19 Carlotte and the same of th	S/U
a)	oad Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality	ding Quality	
d)	oad Camber		Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Y es/140
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture	Link Print	per objects
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History	Property Commence	freezen da varia
a)	Status of ATR's & any others	-	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

of alapha

(Signature)

bot . Dr

NAME:

DESIGNATION: