FIELD INSPECTION REPORT

Date of Inspection: 04.12.2020.			District:- Sitamarhi.		
Division:-RWD, Works Div. Pupri.			Length (km):- 2:050 low		
Name o	of the Road:- Pl	PRI BELMOHA	N 149 PWD ROAD TO	MUCHINO TO	
~ ~	ar rogramme.	MATHER	ANCE		
Packag	e No .:- MR-N	1019-20 pupril	13 Road Id No.: 31 60	42010CF	
Status of the Project: Ongoing/Completed/Under Maintenar			e		
	s a case of:	New Connectivit	y/Up gradation/ Mainte	enance	
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement work order Issued Just Before Electer) In Acrossent Process.				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutments & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railing/slab/approach for bridges			S/SRI/U	
3.	Road Furniture				
a)	Km & 200m stones/Pavement road marking are			Yes/No	
4.	provided and maintained				
-	Compliance History				
a)	Status of ATR	's & any others			

Overall Rating : N/A

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:- RAGBABU

DESIGNATION:- E.E. DOO, GUEDII