FIELD INSPECTION REPORT Last. Changara 54/12/2020 Date of Inspection: District: Chalca Length (Km): 2-020 164 Ulvision: Chalconadan Bathane Name of the Road : MAINTENANCE (New Maintinence Salio ne/Programme: Factorge No.: Road ID No .: Status of the Project : Ongoing/Completed/Under Maintenance — Will is a case of: Hew Connectivity/Up Gradation/ Maintenance 51. No. Parameters to be checked Remarks Pavement 4) Road Junction condition 1:) Condition of Surfacing £. Riding Quality 62 Road Camber Whether free from defects such as visible cracks, exposed aggregates in 18) Case of CC Pavement 1) Contraction Joints provided or not (CC Pavement) (1) Compaction of flank/slope & raincuts if any Cross Drainage 11) Condition of head walls in Hume pipe culverts including its painting 11) Condition of Abutment & Wing walls, Slab in RCC Culverts Condition of railings/slab/approach for Bridges Road Furniture Whether sign board/informatory/cautionary Board/Km & 200m 723 11) Stones/Pavement road markings are provided and maintained Compliance History 1) Status of ATR's & any others Satisfactory (8) Overall Rating Satisfactory but requires improvement (SRI) (Signature) NAME : DESIGNATION:

.