FIELD INSPECTION REPORT

TILLO MOFLO HON REPORT				
Date of Inspection: 06 112 120 20			District: E. Champran.	
Division: Chalaia. Length (Km): 4.90 km			mg:477 km	
Name of the Road: NH-28 to Baisaha.				
Scheme/Programme: MAINTENANCE (NIEw)				The second secon
Package No.: Road ID No.:				
Status of	the Project :	Ongoing/Completed/Under Maintenance		
		New Connectivity/Up Gradation/ Maintenance		
SI. No.	Parameters to be checked Remarks			Pomostra
1,	Pavement			Kemarks
a)	Road Junction condition			
b)	Condition of Surfacing			-
c)	Riding Quality			No.
d)	Road Camber			_
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			-
f)	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any			_
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			_
c)	Condition of railings/slab/approach for Bridges			_
3,	Road Furniture			
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			_
4,	Compliance History			
a)	Status of ATR's & any others			
Overall Rating : Satisfactory (S)				
		Satisfactory (S)		_
		Satisfactory but requires in Unsatisfactory (U)	nprovement (SRI)	
	Ľ	Januara tory (U)		

Remarks: - work yet to be started.

NAME:

06/12/2020

(Signature)

DESIGNATION: