FIELD INSPECTION REPORT

			ALMA OALA	
Date	of Inspection:	02-12-2020	District:	DARBHANGA
Division:		DARBHANGA-2	Length(Km):	
Name of Road:		R.I.O Road Navayanpur Se Bahata tak		
Scheme/Progrmme:		Maintenance		
Package No.		1 10	Road Id No.	319093080
Status of the Project:		Ongoing/Completed/ Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
S No.	Developed to the state of the s			Remarks
1	Pavement	即形態以		
a)	Road Junction condition S/U /			
b)		ondition of Surfacing		
c)	Riding Quality			S/U
d)	Road Camber	1	S/U ~	
e)	Whether free from defects such as visible cracks, exposed			S/U V
	aggregates in case of CC Pavement			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No Yes/No
g)	Compaction of flank /slope & raincuts if any			Yes/No ~
2	Cross Drainage			Alanda a a China
-)	Condition of head walls in Hume pipe culverts including its			
a)	painting			S/SRI/U~
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges			S/SRI/U~
3	Road Furniture			
a)	Whethersign boar	ds/ informatory/ cautionary E	Board / Km &	
	200m stones/ Pavement road markings are provided and			Yes/No
	maintained			105/110
3	Complianace	lianace History		
a)	Status of ATR's & any others			N. A
			· A	,,
verall	Rating:	200	Part .	
		Satisfactory (S)		
		Satisfactory but requires Imp	provement (SRI)	- 10
	V	Unsatisfactory (U)	Cinche (OIII)	. 17
14		and the second	20	20

Name: Rasiv Nayon prosad singh

Designation: S.E R.WD Darbhanga circle