FIELD INSPECTION REPORT

| Date of | f Inspection : | 07/12/2020 | District: Co. 3 | The second secon |
|----------|--|--|---------------------------|--|
| | " - Mah | grafgani | Length (km): | |
| Scheme | of the Road:e/Programme: | Petris of Road | Road Id No.: | o Sapar Julto |
| Packag | 10 No.: - MR-30 |)54 | Road Id No .: | thu ari is a Gol |
| Status | of the Project: | | ed/Under Maintenance | |
| Worki | s a case of: | New Connectivity/ | Up gradation/ Maintenance | Provide the second of the seco |
| Sl. No. | Parameters to be checked Remark | | | |
| 1. | Pavement | The state of the s | | |
| .1) | Road Junction condition | | | 3/U |
| h) | Condition of Surfacing | | | S/U |
| c) | Riding Quality | | | S/U |
| d) | Road Camber | | | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | S/U d Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/No M |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No |
| 2. | Cross Drainage | | | |
| (1) | Condition of head walls in Hume pipe culverts including its painting | | | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/U |
| () | Condition of railings/slab/approach for Bridges | | | S/SŘI/Ú |
| 3. | Road Furniture | | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | Yes/No |
| 4. | Compliance History | | | 3 |
| .1) | Status of ATR's & any others | | | NO, Aory |
| verall R | tating : | Satisfactory (S) | | U |
| | | The second secon | quires Improvement (SRI) | |
| | | Uncaticfactory (II) | | 1 111111 |

Remarks -> Road is damaged due to heavy flood.

(Signature) Avivaxinary

NAME: JIBACHH PRASAD