FIELD INSPECTION REPORT

	F	FIELD INSPECTI	ON REPORT	· · · · · · · · · · · · · · · · · · ·		
Date Of Inspection				choppen 6.14		
Division Piro Length (km):			6.14			
Name o	Name of the Road: Katehour - Kushdehoa					
Scheme/Programme MAINTENANCE						
Packag	e No .: RM/BH/PIR	119/0011	Road Id No.: +040   60.	2034		
Status of the Project : Ongoing/Completeted/Under Maintenance						
Work is a case of:		New Connectivity/	New Connectivity/Up gradation/Maintenance			
SI No.	Parameters to be checked		Remarks			
1	Pavment					
a)	Road Junction condition			S/U		
b)	Condition of Surfacing			S/U		
c)	Riding Quality			S/U		
d)	Road Camber			S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No		
f)	Contraction Joints provided or not (CC Pavement)			Yes/No		
g)	Compaction of flank/slope & raincuts if any			Yes/No		
2	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U		
c)	Condition of railings/slab/approach for Bridges			S/SRI/U		
3	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No		
4	Compliance History					
a)	Status of ATR's & a	ny others				

Overall Rating :		Satisfactory (S)	
		Satisfactory but requires Improvement (SRI)	
		Unsatisfactory (U)	

work has been storated,

Name: AsloKKmm

(Signature)

Desigination