

FIELD INSPECTION REPORT

Date of Inspection : 04/12/2020		District: NANAYAK	
Division : NANAYAK		Length (km):	
Name of the Road: Nandigam Hissa road to odo village.			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance <i>out of maintenance</i>	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU N/A
b)	Condition of Surfacing	SU N/A
c)	Riding Quality	SU N/A
d)	Road Camber	SU N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No N/A
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Note:- The road is out of maintenance

NAME:

[Signature]
(Signature) 04/12/2020