FIELD INSPECTION REPORT

(Paver - Shahkun)

spection: 05/12/2020 District: Bhagalpur		
	1.0/	HITHIO AND DIMENSION (MITTEL)
vame of the Road: Shalkund Pulwang Reo Road Ka	2 Yaki Shed ito Rbs	ations
Scheme / Programme : MAINTENANCE		
Package No.:/Growp No - 69 Road Id No.: 2070 330 1	10.0 /.	
Status of the Project: Ongoing / Completed / Under Maintenance	10 Z C	v. b.,
Vork is a case of: New Connectivity / Up gradation / Maintenance		
SL. No. Parameters to be checked	Remarks	
1. Pavement		~
a) Road Junction condition	S/U 1	
b) Condition of Surfacing	s/u bn go	ing 1
c) Riding Quality	S/U / OA	
d) Road Camber	S/U	
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No \.	- 57
f) Contraction Joints provided or not (CC Pavernent)	Yes/No NA	
g) Cpmpaction of flank/slope & raincuts if any	Yes/No	
2. Cross Drainage		
Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b) Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U NA	
c) Condition of railings/slab/approach for Bridges	S/SRI/U	
3. Road Furniture	10 10 10	
Whether sign boards / informatory / cautionary Board / Km & 200m stones Pavement road markings are provided and maintained.	Yes/No MA	
4. Compliance History		
a) Status of ATR's & any others	NOIL	
verall Rating:	120	1 (1) (1) (1)
Satisfactory (S)		
Satisfactory but requires Improvement (SRI)	NA	
	1 1 1 1	

NAME: Ladto Ramon Single DESIGNATION: ASSISTAND Engineer

(Signature)

05/12/2020