## FIELD INSPECTION REPORT

Dete of Inspection: 0	5-12-2020	District: 13	anka
Date of American		Length (km): 2.28 K.H.	
Division: Banka-	atouction of Ra		there to Hasia Village
	MAINTENANCE	191 10W 10X	aresa 10 199519 Villayo
Scheme/Programme:		Dood Id No.	
Package No.: RM/BA	18AN/19/0011	Koad Id No.:	50103201033
Status of the Project:	Ongoing/Completed/Under Maintenance    Road Id No.: 20703501039		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
	Parameters to l	e checked	Remarks

Work is a case of:	Contact of the Contac
Sl. No. Parameters to be checked	Remarks
1. Pavement	
a) Road Junction condition	S/U or
b) Condition of Surfacing	S/U
c) Riding Quality	√\$/U
d) Road Camber	S/U
e) Whether free from defects such as visible cracks, e aggregates in case of CC Pavement.	exposed Yes/No
f) Contraction Joints provided or not (CC Pavement)	Yes/No
g) Compaction of flank/slope & raincuts if any	Yes/No
12. Cross Drainage	
a) Condition of head walls in Hume pipe culverts including its p	ainting S/SRI/U
b) Condition of Abutment & Wing walls, Slab in RCC culverts	sainting S/SRI/U S/SRI/U
c) Condition of railings/slab/approach for Bridges	S/SRI/U
3. Road Furniture	
a) Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No
4. Compliance History	
a) Status of ATR's & any others	

Overall Rating :

Complete the control of the control	
Satisfactory (S)	satisfactor (s)
Satisfactory but requires Improvement (SRI)	all said
Unsatisfactory (U)	•

(Signature)

NAME: Ashokkumar Sinka

DESIGNATION: Junior Engineer.