## FIELD INSPECTION REPORT

Date of I	nspection: 06. 12. 2020 Di	strict: Banka	
	The second secon	ength (km): 2.37	
Name of	the Road: construction of Road f	rom Banka Belhan PWD	Road Livagora
	Programme: MAINTENANCE		and and
	No: DN/DA/BAN/19/10011 Re	oad Id No.: 207035010	42
Status of	the Project: Ongoing/Completed/Un	der Maintenance	
Work is	a case of: New Connectivity/Up g	2000 CO 100 CO 1	Remarks
Sl. No.	Parameters to be	checked	Remarks
1.	Pavement	and the second s	The second section of the sect
(a)	Road Junction condition		S/U ongoin
	A CONTRACT OF THE PROPERTY OF		S/U orgain
b)	Condition of Surfacing		S/U manix
e)	Riding Quality		S/U 02 00 iv
d)	Road Camber	ou for	
e)	Whether free from defects such a aggregates in case of CC Pavement.	Yes/No N.A	
0	Contraction Joints provided or not (CC Pavement)		Yes/No N. A
g)	Compaction of flank/slope & raincuts if any		Yes/No ongoi w
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U ongo
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U ongo
c)	Condition of railings/slab/approach for Bridges		S/SRI/U N·A
3.	Road Furniture		
3.			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
11)	Status of ATR's & any others		U gamente de la companya de la compa
	The state of the s		

Overall Rating :

Satisfactory (S)	satisfactory (s)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	#

(Signature)

NAME: PRITAM WMAR

DESIGNATION: KE