

FIELD INSPECTION REPORT

Date of Inspection : 04/12/2020		District: PURNEA
Division : BAJST		Length (km): 10.350 km
Name of the Road: NH57 KASBA TO GERWA PATH		
Scheme/Programme: MAINTENANCE		(MR 3059)
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U - NA
b)	Condition of Surfacing	S/U - NA
c)	Riding Quality	S/U - NA
d)	Road Camber	S/U - NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - NA
g)	Compaction of flank/slope & raincuts if any	Yes/No - NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	- NA - (Recently)
Satisfactory but requires Improvement (SRI)	Work has been started
Unsatisfactory (U)	

Gaurav Kumar
(Signature) 04/12/20

NAME: GAURAV KUMAR

DESIGNATION: ASSISTANT ENGINEER