FIELD INSPECTION REPORT

Date of Inspection: 04 · 12 · 20 20 District: - Sitamarh					
Division:-RWD, Works Div. Pupri. Length (km):- 0 · 3			190 k·m		
Name o	f the Road:-Po	KHARBHINDA "	TO BAURA PATH.		
Scheme	/Programme:-	MAINTENA	ANCE		
Package	e No .:- MR-N	19-20-pupri/13	Road Id No.: NEAD	20001944	
		Ongoing/Comple	ted/Under Maintenanc	e	
	s a case of:	New Connectivity	/Up gradation/ Mainte	enance	
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement (work oro) er Passed Tust Bother Blookbu) Dos Agreement proce				
a) .	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutments & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railing/slab/approach for bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sing Km & 200m provided and	Yes/No			
4.	Compliance History				
a)	Status of ATR	's & any others		1/4/20	

N.A-

Overall Rating : N/A

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:- RAMBABU

DESIGNATION: - E.E. RWD - PUPRI