FIELD INSPECTION REPORT

e of In	spection: 0	5/12/2020	District: Tanu		_	
Length (km):			Length (km): 2,20 KH			
me of t	he Road:	Mahader Sima	rio to shandaba		_	
heme/P			To 171 No. 0 01 5 00 F	25	-	
ackage ivo.			Road Id No.: 284110335	327.27		
atus of	the Project:	Ongoing/Completed	VUnder Maintenance		_	
ork is a	a case of:	New Connectivity/L	Jp gradation/ Maintenance	Remark		
l. No.		Paramorers to	be checked			
1.	Pavement	LUCUST ANDRE		S/U	7 7	
a)	Road Junction condition				+	
b)	Condition of Surfacing			S/U	L	
c)	Riding Quality			S/U	0	
d)	Road Camber			S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes Ato		
f)	Contraction Joints provided or not (CC Pavement)			Yes/No		
g)	Compaction of flank/slope & raincuts if any			Yes/No		
2.	Cross Dealing	The twen to the control of the contr		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	· Sec	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U		
c)	Condition of railings/slab/approach for Bridges			S/SRIAL	L Fig.	
3.	Road Furnitu	The state of the s			132	
a)	D1/1 % 700m			YesANø	Yes/Nø	
	Compilarice History 4					
a)	Status of ATR's & any others			N.A		
				W-A	١.	
Overall Rating :		Satisfactory (S)				
			requires Improvement (SRI)			
		Unsatisfactory (U)		9	

April 2 12-20 2 2 12-20

(Signature)

NAME:

DESIGNATION: