

# FIELD INSPECTION REPORT

Date of Inspection:	05.12.2020	District:	Darbhanga.
Division:	RWD WORKS (Dir) Darbhanga-2.	Length(Km):	0.840 KM
Name of Road:	L035- Bhawanipura to Loriga.		
Scheme/Programme:	Maintenance MR-3054 (New-Maint. Policy -2018).		
Package No.	—	Road Id No.	—
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance ✓		
S No.	Parameters to be Checked	Remarks	
<b>1</b>	<b>Pavement</b>		
a)	Road Junction condition	S/U NA	
b)	Condition of Surfacing	S/U NA	
c)	Riding Quality	S/U NA	
d)	Road Camber	S/U NA	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA	
g)	Compaction of flank /slope & raincuts if any	Yes/No NA	
<b>2</b>	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA	
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U NA	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U NA	
<b>3</b>	<b>Road Furniture</b>		
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No NA	
<b>3</b>	<b>Compliance History</b>		
a)	Status of ATR's & any others	NA	
Overall Rating:			

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Not applicable ✓

Name: KUMAR CHANDRA.

Designation: APT. ENGINEER.

(Signature)  
सहायक अभियन्ता  
ग्रामीण कार्य विभाग  
कार्य अवर प्रमंडल, सिंहबाड़ा

\* Heavily submerged & flow of water during flood period road got damaged at several portion  
\* Temporary resurfacing work has been done.  
\* work will start soon.