FIELD INSPECTION REPORT

| | The purious property and a stage case A stag | District: 00-110 | | 7 |
|---|--|--|--|--|
| Date of Inspection: 05.12.2020 District: Banka | | | | |
| Division: Banka-1 Length (km): 3.32 | | | | |
| Name of | the Road: 🕠 | aushbad SBI road - chutia | and the second s | 1 |
| Scheme/Programme: MAINTENANCE Road Id No.: 20703502/30 | | | | |
| | No .: RM/BI | Ongoing/Completed/Under Maintenance | 3502150 | - |
| | f the Project: | New Connectivity/Up gradation/ Maintenance | | |
| | | Remarks | | |
| Sl. No. | 44.5 | Parameters to be checked | | - |
| I. | Pavement | | | |
| a) | Road Junction condition S/U | | | on |
| , | | S/U | one | |
| b) | Condition of S | S/U | on | |
| c) | Riding Quality | S/U | ON | |
| d) | Road Camber | | | |
| e) | Whether free from defects such as visible cracks, exposed yes/No aggregates in case of CC Pavement. | | | N |
| f) | Contraction Joints provided or not (CC Pavement) Yes/ | | | N. |
| g) | Compaction of flank/slope & raincuts if any Yes/No | | | ON |
| 2. | Cross Draina | ge Land | | and the same of th |
| | Condition of head walls in Hume pipe culverts including its painting S/SRI/U | | | 0007. |
| a) | Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U | | | 0 |
| b) | | | S/SRI/U | N. |
| c) | Condition of railings/slab/approach for Bridges S/SRI/U | | | |
| 3. | Road Furniture | | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | |
| 4. | Compliance History | | | None of the last o |
| a) | | 's & any others | | - |
| 10 T | | | | |

Overall Rating :

| Satisfactory (S) | satisfactory (s) |
|---|------------------|
| Satisfactory but requires Improvement (SRI) | 1, () |
| Unsatisfactory (U) | 1 |

(Signature)

NAME: PRITAM KUMAR

DESIGNATION: LE