Data - 6		FIELD INSP	ECTION REPORT	
Division Division	Inspection: 0	3/12/2020	District: Janu'	
Name of the Janua Length (km): 1.050 KH				
Scheme	10	ont REO-ROC	ad to Mahatour	
Packag	NI-	MAINTENANCE		
Status (THE PARTY	Pagaino/Complet	Road Id No.: 2-08041 02	403
Work is	a case of:	New Connectivity	/Up gradation/ Maintenance	
Sl. No.	建工作和工作工程	Patometer		SROMATOR.
1	Pavement		C TRANSPORT OF THE PARTY OF THE	
a)	Poed Investigation 133			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			
d)	Road Camber			S/U m-going
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No. V
Ð	Contraction Joints provided or not (CC Pavement)			Yes/No-N.A
g)	Compaction of flank/slope & raincuts if any			Yes/No
4	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			SISRIAU Work han not be
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U, NA
c)	Condition of railings/slab/approach for Bridges			S/SRI/U A.A
3.	Road Puristare			THE STATE OF
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	eomplancs (it	tory		
a)	Status of ATR's & any others			N-A
Oversil	Rating :			'N.A'
Overall	. Vatura	Satisfactory (S)		
		Satisfactory ha	t requires Improvement (SRI)	

Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

NAME:

(Signature)