06/12/2020 DISTRICT: furn	
02/12/	(C-)
Dhoundalas LENGTH: 3.07	
Blancaiper Approach Road to Dumi	71.
MAINTENANCE	
ROAD ID No.:	
ONGOING/COMPLETED/UNDER MAINTEN	NANCE
NEW CONNECTIVITY/UP GRADATION/MAIN	TENANCE
PARAMETERS TO BE CHECKED	REMARKS
PAVEMENT	
	N·A
	NA
CONDITION FO SURFACING	N-A
RIDING QUALITY	N-A
ROAD CAMBER	
WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	IV·A
	N·A
	Nº H
CROSS DRAINAGE	
CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS	N.A
PAINTING  PAINTI	N. It
	N·A
ROAD FURNITURE	
THE COUNTY BOARD KM & 200 M	5
STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND INTERPRETATIONAL	
COMPLIANCE HISTORY	all Anguar
STATUS OF ATR'S & ANY OTHERS	Q NO AWATT
	_
CATISEACTORY(S)	2
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	
ľ	MAINTENANCE  ROAD ID NO.:  ONGOING/COMPLETED/UNDER MAINTEN  NEW CONNECTIVITY/UP GRADATION/MAIN  PARAMETERS TO BE CHECKED  PAVEMENT  ROAD JUNCTION CONDITION  CONDITION FO SURFACING  RIDING QUALITY  ROAD CAMBER  WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED  AGGREGATES IN CASE FO CC PAVEMENT  CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)  COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY  CROSS DRAINAGE  CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS

Kymars Croupsen

AME: [CL ESIGNATION:

SIGNATURE