FIELD INSPECTION REPORT

Date of Inspection: 05./2.2020		District: Savan (Chapon)		
Division: Metchura		Length (km): 2.231 KH.		
Name of the Road: Ba	cont pur -to	Dhoure habon.		
Scheme/Programme:	MAINTENANCE			
Package No.: Rm/SA	mnx 1010002	Road Id No.: ついろの202030		
Status of the Project:	Ongoing/Completed	/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance			
Sli No.	Data Salasan			

SI No.	Paramoters to be checked	Remarks	
1	Payement	Killar Civil	
a)	Road Junction condition	S/U	1
b)	Condition of Surfacing	S/U	Hot stre
c)	Riding Quality	S/U	Hut San
d)	Road Camber	S/U	}
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ·	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g) :	Compaction of flank/slope & raincuts if any	Yes/No 🗸	
2.4	Cross Drainage	eir de d	e P
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U:)	
b) '	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	xlot stoot
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	51
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) SRI Unsatisfactory (U)

Anded Mortin blow

NAME:

DESIGNATION:

Scanned with CamScanner