## FIELD INSPECTION REPORT

		THE INTERIOR	CHONKETORI		
	f Inspection:	07/12/2020	District: Chabsa (Cas	an)	
Divisio			7	am	
	of the Road:	Balesasa -	- Samtabas_	-	
	e/Programme:	MAINTENANCE	2		
Packag			Road Id No.:		
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of: New Co		New Connectivity/U	Connectivity/Up gradation/ Maintenance 305 9 M/R		
SI. No.		Parameters to	be checked	Remarks	
1.	Pavement				
a)	Road Junction condition			18/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			V S/U	
d)	Road Camber			\_S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/Nov	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No V	
2.	Cross Drainag	e -			
a)	Condition of he	S/SR1/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture	e			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance His	itory			
a) S	Status of ATR's	& any others		-	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Construction of the second

7/12/02 A1E

(Signature)

NAME:

**DESIGNATION:**