## FIELD INSPECTION REPORT

Date o	of Inspection:	03/12/2020	District: Chrbsg (Sa	san)
Divisio	on: Chr		Length (km): 7.2	
Name of the Road: Kohna Bazas - Hwaynapul				
	e/Programme:	MAINTENANCE	)	
Packag			Road Id No.: World	1 . 1 .
	of the Project:		1/Under Maintenance Not 5	12 2001
	s a case of:	The state of the second	Jp gradation/ Maintenance M/	3051
SI. No.		Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction	condition		S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)				Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainag	Profession de la company		
a)	the second of th	The second secon	e culverts including its painting	S/SRI/U
b)				S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture	The state of the s		
a)	Whether sign be stones/Pavement	ooards/informatory/ca troad markings are p	autionary Board/km & 200m rovided and maintained	Yes/No
4.	Compliance His	tory		
Parket Broken der bei bei	Status of ATR's			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	V
Unsatisfactory (U)	

NAME:

**DESIGNATION:** 

Scanned with CamScanner