## FIELD INSPECTION REPORT

Date of Inspection :	112/20	District: 3: 2note	
Division: Szlaz		Length (km): 1.76 Km	
Name of the Road: 3		aika. (9-15)	
Scheme/Programme:	MAINTENANCE	113	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Kork rol- Storked		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
SI. No.	Parameters to	September 1, 1, 2, 4, 2, 2, 2, 3, 1, 2, 4, 2, 4, 2, 1, 2, 1, 2, 1, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2,	

31, 190,	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber ·	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Pordrigzonan DESIGNATION: A.E., Parilos, Storush.

Scanned by CamScanner

(Signature)

N-A