FIELD INSPECTION REPORT

TILLED INTO LOTTON TILL OIL				
Date of Inspection: 05/12/2020 District: E. Champro).
Division: Chakra. Length (Km): 2.730 Kr				
Name of the Road: NH-28 Garesh Baitha House to Birth tela chakbara.				
Scheme/Programme: MAINTENANCE (New))	
Package No.: Road ID No.:				
Status of the Project :		Ongoing/Completed/Under Maintenance		
Work is a case of : New Connectivity/Up Gradatio			dation/ Maintenance	
SI. No.	Parameters to be checked			Remarks
1,	Pavement			
a)	Road Junction condition			N/A
b)	Condition of Surfacing			NA
c)	Riding Quality			NA
d)	Road Camber			N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			-
f)	Contraction Joints provided or not (CC Pavement)			_
g)	Compaction of flank/slope & raincuts if any			_
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
ь)	Condition of Abutment & Wing walls, Slab in RCC Culverts			_
c)	Condition of railings/slab/approach for Bridges			_
3,	Road Furniture			
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			_
4,	Compliance History			
a)	Status of ATR's & any others			
Overall Rating : Satisfactory (S)				
	Overall Rating : Satisfactory (S) Satisfactory but requires improvement (SRI)			
		Unsatisfactory (U)	improvement (SKI)	
		J J.		

Remarks: - work in puogress.

NAME:

OSTISTON

(Signature)