## FIELD INSPECTION REPORT

Date of Inspection: 06-12-2020			District: Darbhange, Length (km): 2.77	
Division: Doubhanga - 2			Length (km): 2.77	
Name of	the Road:	14 (Chhatwan		793
Scheme/Programme: MAINTENAN		MAINTENANCE	E MR 3054 Nonp-2018	
Package	No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is	a case of:	New Connectivity	/Up gradation/ Maintenance	n a salara de la compa
SI. No.	<b>美国特别</b>	Parameters	to be checked	Remarks
1.	Payement	A Maria		
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drain	CONTRACTOR CONTRACTOR		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
1.)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U

Overall Rating

b)

c)

3.

a)

4.

a)

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Not applicante

Condition of Abutment & Wing walls, Slab in RCC culverts

stones/Pavement road markings are provided and maintained

Whether sign boards/informatory/cautionary Board/km & 200m

Condition of railings/slab/approach for Bridges

(Signature)

S/SRI/U

Yes/No

DESIGNATION:

NAME: H 00080

Road Furniture

Compliance History

Status of ATR's & any others