FIELD INSPECTION REPORT 06/12/2020 Date of Inspection : District: Jagdishpur Ara. Length (km): I modes voti rement the Road: Repair of Road from O sai to Bola. MAINTENANCE Old maintenance believe Programme: 10401708067 Road Id No .: Package No.: Ongoing/Completed/Under Maintenance Under Majutarance Status of the Project: New Connectivity/Up gradation/ Maintenance Maintenance Work is a case of: Parameters to be checked Remarks Payement S/U Road Junction condition 5/11 Condition of Surfacing ŠIU Riding Quality ŠIU Road Camber Whether free from defects such as visible cracks, exposed Yes/No aggregates in case of CC Payement. Yes/No Contraction Joints provided or not (CC Pavement) Yes/No Compaction of flank/slope & raincuts if any Cross Drainage Condition of head walls in Hume pipe culverts including its painting S/SRI/U Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U Condition of railings/slab/approach for Bridges S/SRI/U Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained Compliance History 4. Status of ATR's & any others Coverall Rating Satisfactory (S) Satisfactory but requires Improvement (SRI) SRT Unsatisfactory (U) NAME: Gayonand regrate.