FIELD INSPECTION REPORT

Date of Inspection: 04.12.2020		District: Banka	
Division: Banka-1		Length (km): 12.40	
	pain of road to	from Belhon sandcept	
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.: 20703508113	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
e)	Riding Quality	S/U
d)	Road Camber	√8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
t)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	9-3-4-7 9-3-4-7 1-3-3-7
a)	Condition of head walls in Hume pipe culverts including its painting	8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	8/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	and the second pass of the second pass in the second pass of the secon

Overall Rating :

Satisfactory (S)	The state of the s
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	Unintistad

(Signature)

NAME: BOOTOND COLORD

DESIGNATION: E-E