


FIELD INSPECTION REPORT

Date Of Inspection	2.12.2020	District	Bhojpur
Division - PIRo, Block- PIRo		Length (km):	10.65
Name of the Road:	Agiaon Sonbarsa mukhya path to Akarahi talga		
Scheme/Programme	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl No.	Parameters to be checked	Remarks	
1	Pavment		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No N'D	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N'D	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N'D	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N'D	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N'D	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	✓ S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Sushil Kumar


(Signature)

Designation Junior Engineer