FIELD INSPECTION REPORT

Date of Inspection :	2.12.20	District: Rohaus
Division: Sasgram - 1		Length (km): 3.08 km
Name of the Road: 8	ir Norgar PWD	Road to Bharendua (B'FR-831)
Scheme/Programme:	MAINTENANCE	A Plante word (D 2/(& 2))
Package No.:		Road Id No.;
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
	A CONTRACTOR OF THE PROPERTY O	

S1. No.	Parameters to be checked	Remarks
1.	Pavement	er tilk ar i tilk mi
a)	Road Junction condition	S/U
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cress Drainage day and a second a second and	die chiches
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
2	Road Furniture	21.77
2)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4. 2	Compliance History	A TERMINE
E)	Status of ATR's & any others	MO

Overall Rating

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	Harris Harris
Unsatisfactory (U)	de a

for 30

Ben work

(Signature)

NAME:

DESIGNATION: