## FIELD INSPECTION REPORT

Date of Inspection :	The state of the s	District: Samaslipuz
Division: Samartibus		Length (km): 4.00 km
Name of the Road: M	DRIBHOTTI CLOU	ile) la rehatauna
Scheme/Programme:	MAINTENANCE	the second secon
Package No.:	Electrical straints there was bother paraways and	Road Id No.: 320101008.59
Status of the Project:	Ongoing/Completed/Under,Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition Work in Progress	.5/U	
b)	Condition of Surfacing 22	.s/U	
c)	Riding Quality	S/U	
d)	Road Camber	.S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/JU	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	8/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	nil	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	

(Signature) M

NAME: Véveranant