FIELD INSPECTION REPORT

Name of the Scheme/Processing Name of the Package Name of the Name		2.12.2020 Block-PIRO		Length (kn	A RESIDENCE OF THE PERSON NAMED IN	od pur	
cheme/Pr Package N							
ackage N	1.40	REO ROGO	1 - B	aisacli	hi	6.78)	
ackage N	rogramme	MAINTENANCE					
	No.: RMIBHIPIR	11910006	Road Id N	lo.: 104	61 L	.02060	
Status of the Project :		Ongoing/Completeted/Under Maintenance					
Work is a	case of:	New Connectivity/U	p gradatio	n/Maintena	nce V		
SI No. Parameters to be checked			ced		T	Remarks	
I	Pavment	nt					
a) I	Road Junction condition				T	VS/U	
b) (Condition of Surfacing				\top	VS/U	
c)]	Riding Quality					VS/U	
	Road Camber					V \$/U	
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement				tes	Yes/No N.	
f)	Contraction Joints provided or not (CC Pavement)					Yes/No N'A	
g)	Compaction of flank/slope & raincuts if any					Yes/No~	
2	Cross Drainage						
a)	Condition of head walls in Hume pipe culverts including its painting				ing	S/SRI/U N·	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts					S/SRI/U N·A	
c)	Condition of railings/slab/approach for Bridges					S/SRI/U N 4	
3	Road Furniture						
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained					Vyes/No	
4	Compliance History						
a)	Status of ATR's & any others						
						"s"	
Overall Rating :		Satisfactory (S)		. 10	DI	3	
		Satisfactory but requires Improvement (SRI)			KI)		
		Unsatisfactory (U)	1	in Karalas	11	Affrica	

Designation $-J \cdot \mathcal{E}$

Scanned with CamScanner