FIELD INSPECTION REPORT

Date C		TELD INSPECT 2・12・20 20	ION REP		hospur	
Division - PIRO, BIOK- PIRO Length (km):					6.47	
	of the Road:				0 17	
	e/Programme	Sanaya - Baina				
			Pond Id N	0: 454	-0.66	
	14 1101111	' /	Koad Id IV	0.: 104016	02065	
Status of the Project :		Ongoing/Completeted/Under Maintenance				
Work is a case of:		New Connectivity/Up gradation/Maintenance V				
SI No.		Parameters to be checked Ro			Remarks	
I	Payment Work Not Start					
a)	Road Junction condition			S/U		
b)	Condition of Surfacing			S/U		
c)	Riding Quality			S/U		
d)	Road Camber			S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No		
f)	Contraction Joints provided or not (CC Pavement)			Yes/No		
g)	Compaction of flank/slope & raincuts if any			Yes/No		
2	Cross Drainage			I		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U		
)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U		
:)	Condition of railings/slab/approach for Bridges			S/SRI/U		
,	Road Furniture					
)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No		
	Compliance History					
1)	Status of ATR's & any	others				

Overall Rating	:	Satisfactory (S)	
		Satisfactory but requires Improvement (SRI)	
		Unsatisfactory (U)	

Sughil Kumar

Tyniar Ergineer Name:

(Signature)

Desigination