ate Of I	Inspection 53	FIELD INSPECT		District Bhosp	Wr
ivision Piro				Length (km):	
ame of	the Road:	Koshdihra	TO	Bar Hygr	
cheme/Programme			MAINTENANCE		
ackage	No .: RM/BH/	PIR/19/0009		dNo.: 104016	04116
	f the Project :	Ongoing/Complet	teted/Unde	er Maintenance	
Work is a case of:		The state of the s	New Connectivity/Up gradation/Maintenance		
I No.		Parameters to be of	lecked	141	Remarks
	Pavment				671
1)	Road Junction condition				√8/U
0)	Condition of Surfacing			√S/U	
0)	Riding Quality				~8/U
d)	Road Camber				√S/U
e)	Whether free from defects such as visible clasks, exposes age				Yes/No
n	Contraction Joints provided or not (CC Pavement)				Vés/No
g)	Compaction of flank/slope & raincuts if any				Yes/No
2	Cross Drainage 8/SRI/U				
	Condition of head walls in Hume pipe culverts including its painting				
a)	Condition of Abutment & Wing walls, Slab in RCC culverts				N. # SISKIN
b)	Condition of railings/slab/approach for Bridges			N-A S/SRI/U	
c)	Condition of family				
3	Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m Yes/				Yes/No
a)	stones/Pavemen				
4	Compliance History				-
a)	Status of ATR's	& any others			

			46
Ont	anne D	900	ARALAS.
111	CIME	1 250	ting

Satisfactory (S)	13)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	_

Name: Kamlesh Kumar.

3/12/2020 (Signature)