FIELD INSPECTION REPORT

		07/12/2020.		Bhojp	uz, Ara
	Jagdi	shpur, Aa.	Length (km):		13 Km.
	the Roads	Le 33-Banahi	lose to Dubant Tola	(VR-	33)
	"Programme:	MAINTENANC	E-New Maintenace	folie	1-2018.
La Lage No.:					702014
	of the Projects		ted/Under Maintenance	ong	own .
	is a case of:	New Connectivit	wUp gradation/ Maintenance /	Mein	terfree
di Trus.		Parameters to be checked			Remarks
	Pavement	Pavement			
	Road Junction	condition			Sitt
	Condition of 8	Condition of Surfacing			SAL
	Riding Quality	Riding Quality			
	Road Camber				Š/U
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			osed	Yes/No
	Contraction Joints provided or not (CC Pavement)				Yes/No
	Compaction of flank/slope & raincuts if any				Yes/No
	Cross Drainage				,
	Condition of head walls in Hume pipe culverts including its painting			ting	S/SRI/U
	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
	Condition of railings/slab/approach for Bridges				S/SRI/U
	Road Furniture				
	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained				Yes/No
	Compliance His	story			
	Status of ATR's	& any others			
	orland to				
	lating :	Satisfactory (S)			S
		Satisfactory but a	requires Improvement (SRI)	4
		Unsatisfactory (U			