

FIELD INSPECTION REPORT

Date of Inspection:	05.12.2020	District:	Darbhanga.
Division:	RWD works (Div.) Darbhanga-2	Length(Km):	2.00 K.M.
Name of Road:	PWD path to Harisharpur Tak.		
Scheme/Programme:	Maintenance MR-3054.		
Package No.	—	Road Id No.	—
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance ✓		

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank /slope & raincuts if any	Yes/No NA
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U NA
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U NA
3	Road Furniture	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No ✓
3	Compliance History	
a)	Status of ATR's & any others	NA


Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

* Due to submergence & flow of flood water, such road is badly affected, top layer is fully washed out. Road section lost.

Name: KUMAR CHANDRAJ. Permanent restoration work.

Designation: A.E.T. ENGINEER, estimate to be prepared now.


 सहायक अभियन्ता
 (Signature) प्रामाणिक कार्य विभाग
 कार्य अवर प्रमंडल, सिंहबाड़ा