FIELD INSPECTION REPORT

		FIELD INSPECTION	REPORT	
Date of Inspection:		05-12-2020	District:	Darbhanga.
Division:		Worlds (DIV.) Desobhonge-2,	Length(Km):	CONTRACTOR OF THE SAME OF
Name of Road:		Mos (Div) Doshbarge-2, Length (Km): 8.00 Km To 2 to Bestruli.		
Scheme/Progrmme:		Maintenance MR-3054.		
Package No.			Road Id No.	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
Status of the Project:		Ongoing/Completed/ Under Maintenance —		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
S No.				Remarks
1	Pavement			
a)	Road Junction condition			
b)	Condition of Surfacing			√S/₩¹
c)	Riding Quality .			~5/#
d)	Road Camber			√\$/#
e)	Whether free from defects such as visible cracks, exposed			5/-5
	aggregates in case of CC Pavement			Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)			Yes/No NA
g)	Compaction of flank /slope & raincuts if any			√Yes/No
2	<b>Cross Draina</b>	ge		
a)	Condition of head walls in Hume pipe culverts including its painting			<del>S/SRI/</del> U ⋈ <sup>Ą</sup>
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			S/SRI/U NA
c)	Condition of railing /slabs/ approach for Bridges			S/SRI/U NA
3	Road Furniture			
a)	Whethersign boards/informatory/cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained			Yes/No
3	Complianace History			
a)	Status of ATR's & any others			
			,	
)veral	l Rating:	* 34 j		,,
,		Satisfactory (S)		
		Satisfactory but requires Improvement (SRI)		
		Unsatisfactory (U)		7/=

Name: KUMAR CHANDRAT Designation: ASTT-ENGINEER.

(Signatureमहायक अभियन्ता ग्रामीण कार्य विभाग कार्य अवर प्रमंडल, सिंहबाड़ा

Scanned with CamScanner