FIELD INSPECTION REPORT

		FIELD INSPECTION	REPURI	
Date of Inspection:		05.12.2020	District:	Darbhanga.
Division:		RWD Works (Div) Darblanga-R	The second secon	9.00 KM.
Name of Road:		Harihorpor Chauk se REO path Nimrauli Tak.		
Scheme/Progrmme:		Maintenance MR-3054		
Package No.			Road Id No.	
Status of the Project:		Ongoing/Completed/Under Maintenance		
		New Connectivity/Up gradation/ Maintenance		
Work is a case of:				Remarks
S No.	P	Parameters to be Checcked		
1	Pavement			
a)	Road Junction condition			VS/U
b)	Condition of Surfacing			VS/#
c)	Riding Quality			√ S/ U
d)	Road Camber			V8/H
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)			Yes/No NA
	Compaction of flank /slope & raincuts if any			Yes/No NA
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U-NA
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			S/SRI/U NA
c)	Condition of railing /slabs/ approach for Bridges			S/SRI/U NA
3	Road Furniture			
a)	Whethersign boards/informatory/cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained			Yes /No
3	Complianace History			
a)	Status of ATR's & any others		NA.	
Overall Rating:				
		Satisfactory (S)	CODY	3/
		Satisfactory but requires Im	provement (SKr)	
		Unsatisfactory (U)		5/2

Name: KUMAR CHANDRAT.

Designation: ASTT. ENGLNEER.

Seemand with ComPensage

जिल्लायक अभियन्ता Signatur भीण कार्य विभाग जिल्लाय अवर प्रमंडल, सिंहबाड़ा