FIELD INSPECTION REPORT

Date of Inspection: 7.12,20		District: Magana	
Division: Mojava		Length (Km):- 2ヶチムン	
Name of	Road: Magaria Bakhon	District: Mogara. Length (Km): 2750 PWP Road to Bhadas Pa	rwy.
Scheme/Programme:- N-ew MR.		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project: - Swifacichesiis		Ongoing/Complete/Under Maintenance	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters	to be cheeked	Remarks
1.	Pavement		
a)	Road Junction Condition		S/U
b)	Condition of Surface		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contruction Joints provided or not (CC Pavement) Yes/No		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		io de la familia de la composición dela composición de la composición dela composición dela composición dela composición de la composición dela composición del composición dela comp
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/ Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		AGE OF
a)	Status of ATR's & any others		140

Overall Rating:

Satisfactory (S)	5	
Satisfactory but requires Inprovement (SRI)		
Unsatisfactory (U)	4	

(Signature) 7/2,200
56/Whosave