

FIELD INSPECTION REPORT

Date of Inspection : 6.12.2020 District: Purnima
 Division : Baisi Length (km): 1.520KM
 Name of the Road: Asja to Gafli
 Scheme/Programme: MAINTENANCE
 Package No.: MR-N 19-20 Baisi/02 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SRI
b)	Condition of Surfacing	✓SRI
c)	Riding Quality	✓SRI
d)	Road Camber	SRI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes No NA
g)	Compaction of flank/slope & raincuts if any	✓Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓SRI
c)	Condition of railings/slab/approach for Bridges	SRI NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓Yes No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

"S"

6/12/2020
 A.E
 (Signature)

Baisa

NAME:

Asim Kumar